Contract Title: DPW Operation and Maintenance Activities
Location: Vicksburg, MS
Surveillance Guide Number: 1

1. Contract Requirement: Prepare and Provide Submittals (Phase-In Period)

		<u>Performance</u>		
<u>Per</u>	formance Indicator	<u>Category</u>	<u>Paragraph</u>	MADR
a.	Prepare submittals in accordance with the PWS.	Quality	C.1.5.2.2, C.1.5.3, C.1.5.4, C.1.6.4.6, C.1.6.6, C.1.7.2, C.1.7.5, C.1.7.6, C.1.7.3, C.1.8.1, C.1.8.5, C.1.8.7	2.5%
	Prepare all records and reports within the specified time frame.	Timeliness	C.1.5.2.2, C.1.5.3, C.1.5.4, C.1.6.4.6, C.1.6.6, C.1.7.2, C.1.7.5, C.1.7.6, C.1.7.3, C.1.8.1, C.1.8.5, C.1.8.7	2.5%

- 2. Primary Method of Surveillance: 100% Inspection
- 3. Quantity of Work: The quantity of work will vary depending on the submittals performed by the SP in that month.
- 4. Level of Surveillance: Not applicable for 100% Inspection.
- 5. Sample Size: Not applicable for 100% Inspection.

Minimum Surveillance:

Normal Surveillance:

- 6. Sampling Procedures: Not applicable for 100% Inspection.
- 7. <u>Evaluation Procedures</u>: After checking that all required items have been included in each submittal, the COTR will verify and document the discrepancies in the chosen items. Minor mistakes or omissions will not count as defects unless the mistake or omission is a recurring problem which

has been brought to the attention of the SP in the past. If a submittal contains a major mistake or omission, or has not been submitted on time, it will be considered defective and count as a defect.

8. <u>Analysis of Results</u>: At the end of the month, the COTR will use the Evaluation Summary sheet to summarize all the information on the Evaluation Worksheets and compute the ODR for each performance indicator. The ODR is calculated by dividing the total number of observed by the total population of services so that:

- 9. <u>Suggested Action</u>: The SP should be notified monthly as to whether work performance has been satisfactory or not. If the SP's performance was unsatisfactory, a Contract Discrepancy Report should be issued and other actions, such as increasing the level of surveillance, may be considered.
- 10. <u>Attachments</u>: Forms to be used in the evaluation process include the evaluation worksheets, evaluation summaries, and Contract Discrepancy Reports. Evaluation worksheets and summaries are included in the Surveillance Plan. The Contract Discrepancy Report is included as Attachment 1.

Contract Title: DPW Operation and Maintenance Activities
Location: Vicksburg, MS
Surveillance Guide Number: 2

1. Contract Requirement: Prepare, Maintain, and Provide Records, Reports, and Submittals

<u>Pe</u>	erformance Indicator	<u>Performance</u> <u>Category</u>	<u>Paragraph</u>	MADR
a.	Prepare, submit, and maintain complete and accurate records and reports.	Quality	C.1.5.2.2, C.1.5.3, C.1.5.4, C.1.6.4.6, C.1.6.7, C.1.6.8, C.1.6.10, C.1.6.12, C.1.7.2, C.1.7.3, C.1.7.4.1, C.1.7.5, C.1.7.6, C.1.8.1, C.1.8.3, C.1.8.5, C.1.8.7, C.1.9, C.1.10	2.5%
b.	Prepare all records and reports within the specified time frame.	Timeliness	C.1.5.2.2, C.1.5.3, C.1.5.4, C.1.6.4.6, C.1.6.7, C.1.6.8, C.1.6.10, C.1.6.12, C.1.7.2, C.1.7.3, C.1.7.4.1, C.1.7.5, C.1.7.6, C.1.8.1, C.1.8.3, C.1.8.5, C.1.8.7, C.1.9, C.1.10	2.5%

- 2. Primary Method of Surveillance: Planned Sampling
- 3. <u>Quantity of Work</u>: The quantity of work will vary depending on the requirements performed by the SP in that month.
- 4. <u>Level of Surveillance</u>: The Normal Surveillance Level will be used initially. If the Observed Defect Rate (ODR) is less than the AQL, the Minimum Surveillance Level may be used. If, at the Minimum Surveillance Level, the ODR exceeds the AQL, inspections should then return to the Normal Surveillance Level. If, at the Normal Surveillance Level, the ODR exceeds the AQL for two consecutive months, the taking of additional samples should be considered.
- 5. Sample Size:

Minimum Surveillance: 5% of items in SP records, reports, and submittals

Normal Surveillance: 15% of items in SP records, reports, and submittals

The percentage of samples and the number of inspections that arise from them may be adjusted based upon changing conditions and local requirements.

- 6. <u>Sampling Procedures</u>: Monthly, the COTR will randomly select 15% of the required items to sample under Normal Surveillance. If Minimum Surveillance is being applied, the COTR will randomly select 5% of the required items to sample.
- 7. Evaluation Procedures: After checking that all required items have been included in each submittal, the COTR will verify and document the discrepancies in the chosen items. Minor mistakes or omissions will not count as defects unless the mistake or omission is a recurring problem which has been brought to the attention of the SP in the past. If a submittal contains a major mistake or omission, or has not been submitted on time, it will be considered defective and count as a defect.
- 8. <u>Analysis of Results</u>: At the end of the month, the COTR will use the Evaluation Summary sheet to summarize all the information on the Evaluation Worksheets and compute the ODR for each performance indicator. The ODR is calculated by dividing the total number of observed by the total population of services so that:

- 9. <u>Suggested Action</u>: The SP should be notified monthly as to whether work performance has been satisfactory or not. If the SP's performance was unsatisfactory, a Contract Discrepancy Report should be issued and other actions, such as increasing the level of surveillance, may be considered.
- 10. <u>Attachments</u>: Forms to be used in the evaluation process include the evaluation worksheets, evaluation summaries, and Contract Discrepancy Reports. Evaluation worksheets and summaries are included in the Surveillance Plan. The Contract Discrepancy Report is included as Attachment 1.

Contract Title: DPW Operation and Maintenance Activities
Location: Vicksburg, MS
Surveillance Guide Number: 3

1. Contract Requirement: Clean Debris From Around Gates and Hydraulic Barriers

		<u>Performance</u>		
Performance Indicator		<u>Category</u>	<u>Paragraph</u>	MADR
a.	Perform work in accordance with all applicable professional and quality standards.	Quality	C.5.1.2.1	4.0%
b.	Perform work in accordance with required time frames.	Timeliness	C.5.1.2.1	4.0%

- 2. Primary Method of Surveillance: 100% Inspection
- 3. Quantity of Work:
- 4. Level of Surveillance: Not applicable for 100% Inspection.
- 5. Sample Size: Not applicable for 100% Inspection.

Minimum Surveillance:

Normal Surveillance:

- 6. Sampling Procedures: Not applicable for 100% Inspection.
- 7. <u>Evaluation Procedures</u>: The COTR will verify that the work is performed in accordance with the specifications and specified time frames. A timeliness defect is the percentage of time that work is completed or responded to, as appropriate, past the KO approved or PRS-specified timeliness requirement. Each output that does not meet the specified requirements will constitute a defect.
- 8. <u>Analysis of Results</u>: At the end of the month, the COTR will use the Evaluation Summary sheet to summarize all the information on the Evaluation Worksheets and compute the ODR for each performance indicator. The ODR is calculated by dividing the total number of observed by the total population of services so that:

- 9. <u>Suggested Action</u>: The SP should be notified monthly as to whether work performance has been satisfactory or not. If the SP's performance was unsatisfactory, a Contract Discrepancy Report should be issued and other actions, such as increasing the level of surveillance, may be considered.
- 10. <u>Attachments</u>: Forms to be used in the evaluation process include the evaluation worksheets, evaluation summaries, and Contract Discrepancy Reports. Evaluation worksheets and summaries are included in the Surveillance Plan. The Contract Discrepancy Report is included as Attachment 1.

Contract Title: DPW Operation and Maintenance Activities
Location: Vicksburg, MS
Surveillance Guide Number: 4

1. Contract Requirement: Treat Sanitary Sewer Manholes and Lift Stations

		<u>Performance</u>		
<u>Pe</u>	erformance Indicator	<u>Category</u>	<u>Paragraph</u>	MADR
a.	Perform work in accordance with all applicable professional and quality standards.	Quality	C.5.2.3.1.1, C.5.2.3.1.2	4.0%
b.	Perform maintenance in accordance with specified schedule.	Timeliness	C.5.2.3.1.1, C.5.2.3.1.2	4.0%

- 2. Primary Method of Surveillance: Planned Sampling and Incidental Inspections
- 3. Quantity of Work: The quantity of work is the number of lift stations and manholes.
- 4. <u>Level of Surveillance</u>: The Normal Surveillance Level will be used initially. If the Observed Defect Rate (ODR) is less than the AQL, the Minimum Surveillance Level may be used. If, at the Minimum Surveillance Level, the ODR exceeds the AQL, inspections should then return to the Normal Surveillance Level. If, at the Normal Surveillance Level, the ODR exceeds the AQL for two consecutive months, the taking of additional samples should be considered.

#### 5. Sample Size:

Minimum Surveillance: 10% of the Manholes and Liftstations

Normal Surveillance: 20% of the Manholes and Liftstations

The percentage of samples and the number of inspections that arise from them may be adjusted based upon changing conditions and local requirements.

- 6. <u>Sampling Procedures</u>: At the beginning of each month, the COTR will plan to select 20% of the manholes and liftstations to sample under Normal Surveillance. If Minimum Surveillance is being applied, the COTR will plan to select 10% of the manholes and liftstations for surveillance. Selected manholes and liftstations will be chosen to ensure geographical spread.
- 7. <u>Evaluation Procedures</u>: The COTR will evaluate the SP's performance based upon Planned Sampling, and Incidental Inspections dictated by observed irregularities.

- a. Planned Inspections. For each lift station or manhole selected, the COTR will travel to the site of the work location to determine whether the SP met the required response time, completed the work within the required time, and performed work in accordance with applicable professional and quality standards. A preprinted Evaluation Worksheet will be completed at the time of the evaluation of the service.
- b. Incidental Inspection Performance. If defective conditions are discovered which are not part of the planned inspections, a separate Evaluation Worksheet will be annotated with the same information as a regular worksheet, noting that this is an incidental inspection. When a trend in defects is noted during the course of regular scheduled inspections, incidental inspections may also be used to determine the magnitude of the defects for this specific work item.
- 8. <u>Analysis of Results</u>: At the end of the month, the COTR will use the Evaluation Summary sheet to summarize all the information on the Evaluation Worksheets and compute the ODR for each performance indicator. The ODR is calculated by dividing the total number of observed by the total population of services so that:

$$ODR = \frac{\text{Total Number of Observed Defect}}{\text{Total Population}} \times 100$$

- 9. <u>Suggested Action</u>: The SP should be notified monthly as to whether work performance has been satisfactory or not. If the SP's performance was unsatisfactory, a Contract Discrepancy Report should be issued and other actions, such as increasing the level of surveillance, may be considered.
- 10. <u>Attachments</u>: Forms to be used in the evaluation process include the evaluation worksheets, evaluation summaries, and Contract Discrepancy Reports. Evaluation worksheets and summaries are included in the Surveillance Plan. The Contract Discrepancy Report is included as Attachment 1.

Contract Title: DPW Operation and Maintenance Activities
Location: Vicksburg, MS
Surveillance Guide Number: 5

1. Contract Requirement: Test Fire Hydrants

	<u>Performance</u>		
Performance Indicator	<u>Category</u>	<u>Paragraph</u>	MADR
Perform work in accordance with all applicable professional and quality standards.	Quality	C.5.2.3.1.3	4.0%
b. Perform maintenance in accordance with specified schedule.	Timeliness	C.5.2.3.1.3	7.0%
c. Maintain complete and accurate records of work.	Reporting	C.5.2.3.1.3	4.0%

- 2. Primary Method of Surveillance: Planned Sampling and Incidental Inspections
- 3. Quantity of Work: The quantity of work is the number of fire hydrants.
- 4. <u>Level of Surveillance</u>: The Normal Surveillance Level will be used initially. If the Observed Defect Rate (ODR) is less than the AQL, the Minimum Surveillance Level may be used. If, at the Minimum Surveillance Level, the ODR exceeds the AQL, inspections should then return to the Normal Surveillance Level. If, at the Normal Surveillance Level, the ODR exceeds the AQL for two consecutive months, the taking of additional samples should be considered.

#### 5. Sample Size:

Minimum Surveillance: 10% of the Fire Hydrants

Normal Surveillance: 20% of the Fire Hydrants

The percentage of samples and the number of inspections that arise from them may be adjusted based upon changing conditions and local requirements.

- 6. <u>Sampling Procedures</u>: At the beginning of each year, the COTR will plan to select 20% of the fire hydrants to sample under Normal Surveillance. If Minimum Surveillance is being applied, the COTR will plan to select 10% of the fire hydrants for surveillance. Selected fire hydrants will be chosen to ensure geographical spread.
- 7. <u>Evaluation Procedures</u>: The COTR will verify that the work is performed in accordance with the specifications and specified time frames. A timeliness defect is the percentage of time that work is completed or responded to, as appropriate, past the KO approved or PRS-specified timeliness

requirement. Each output that does not meet the specified requirements will constitute a defect.

- a. Planned Inspections. For each fire hydrant selected, the COTR will travel to the site of the work location to determine whether the SP met the required response time, completed the work within the required time, and performed work in accordance with applicable professional and quality standards. A preprinted Evaluation Worksheet will be completed at the time of the evaluation of the service.
- b. Incidental Inspection Performance. If defective conditions are discovered which are not part of the planned inspections, a separate Evaluation Worksheet will be annotated with the same information as a regular worksheet, noting that this is an incidental inspection. When a trend in defects is noted during the course of regular scheduled inspections, incidental inspections may also be used to determine the magnitude of the defects for this specific work item.
- 8. <u>Analysis of Results</u>: At the end of the month, the COTR will use the Evaluation Summary sheet to summarize all the information on the Evaluation Worksheets and compute the ODR for each performance indicator. The ODR is calculated by dividing the total number of observed by the total population of services so that:

- 9. <u>Suggested Action</u>: The SP should be notified monthly as to whether work performance has been satisfactory or not. If the SP's performance was unsatisfactory, a Contract Discrepancy Report should be issued and other actions, such as increasing the level of surveillance, may be considered.
- 10. <u>Attachments</u>: Forms to be used in the evaluation process include the evaluation worksheets, evaluation summaries, and Contract Discrepancy Reports. Evaluation worksheets and summaries are included in the Surveillance Plan. The Contract Discrepancy Report is included as Attachment 1.

Contract Title: DPW Operation and Maintenance Activities
Location: Vicksburg, MS
Surveillance Guide Number: 6

1. Contract Requirement: Inspect Aerial Distribution Lines

		<u>Performance</u>		
Performance Indicator		Category	<u>Paragraph</u>	<u>MADR</u>
a.	Perform inspection as specified and provide COTR with a list of deficiencies.	Quality	C.5.2.3.2.2	4.0%
b.	Perform inspection in accordance with specified schedule and prepare records and reports within the specified time frame.	Timeliness	C.5.2.3.2.2	7.0%
C.	Provide complete and accurate records of work.	Reporting	C.5.2.3.2.2	4.0%

- 2. Primary Method of Surveillance: Planned Sampling and Incidental Inspections
- 3. Quantity of Work: The quantity of work is the number of electrical distribution poles.
- 4. <u>Level of Surveillance</u>: The Normal Surveillance Level will be used initially. If the Observed Defect Rate (ODR) is less than the AQL, the Minimum Surveillance Level may be used. If, at the Minimum Surveillance Level, the ODR exceeds the AQL, inspections should then return to the Normal Surveillance Level. If, at the Normal Surveillance Level, the ODR exceeds the AQL for two consecutive months, the taking of additional samples should be considered.

#### 5. Sample Size:

Minimum Surveillance: 5% of the Electrical Distribution System Poles

Normal Surveillance: 10% of the Electrical Distribution System Poles

The percentage of samples and the number of inspections that arise from them may be adjusted based upon changing conditions and local requirements.

- 6. <u>Sampling Procedures</u>: At the beginning of each year, the COTR will select 10% of the required items in each submittal to sample under Normal Surveillance. If Minimum Surveillance is being applied, the COTR will select 5% of the required items in each submittal to sample.
- 7. <u>Evaluation Procedures</u>: The COTR will evaluate the SP's performance based upon Planned Sampling, and Incidental Inspections dictated by observed irregularities.

- a. Planned Inspections. For each pole selected, the COTR will travel to the site of the work location to determine whether the SP performed the work within the required time, and performed work in accordance with applicable professional and quality standards. A preprinted Evaluation Worksheet will be completed at the time of the evaluation of the service.
- b. Incidental Inspection Performance. If defective conditions are discovered which are not part of the planned inspections, a separate Evaluation Worksheet will be annotated with the same information as a regular worksheet, noting that this is an incidental inspection. When a trend in defects is noted during the course of regular scheduled inspections, incidental inspections may also be used to determine the magnitude of the defects for this specific work item.
- 8. <u>Analysis of Results</u>: At the end of the month, the COTR will use the Evaluation Summary sheet to summarize all the information on the Evaluation Worksheets and compute the ODR for each performance indicator. The ODR is calculated by dividing the total number of observed by the total population of services so that:

- 9. <u>Suggested Action</u>: The SP should be notified monthly as to whether work performance has been satisfactory or not. If the SP's performance was unsatisfactory, a Contract Discrepancy Report should be issued and other actions, such as increasing the level of surveillance, may be considered.
- 10. <u>Attachments</u>: Forms to be used in the evaluation process include the evaluation worksheets, evaluation summaries, and Contract Discrepancy Reports. Evaluation worksheets and summaries are included in the Surveillance Plan. The Contract Discrepancy Report is included as Attachment 1.

Contract Title: DPW Operation and Maintenance Activities
Location: Vicksburg, MS
Surveillance Guide Number: 7

1. Contract Requirement: Inspect and Test Emergency Lighting Systems and Exit Lights

		<u>Performance</u>		
<u>P</u>	erformance Indicator	Category	<u>Paragraph</u>	MADR
a.	Perform inspection as specified and provide COTR with a list of deficiencies.	Quality	C.5.3.3.2	2.5%
b.	Perform inspection in accordance with specified schedule and prepare records and reports within the specified time frame.	Timeliness	C.5.3.3.2	4.0%
C.	Provide complete and accurate records of work.	Reporting	C.5.3.3.2	4.0%

- 2. Primary Method of Surveillance: Planned Sampling
- 3. Quantity of Work: The quantity of work is the number of exit signs and emergency lights.
- 4. <u>Level of Surveillance</u>: The Normal Surveillance Level will be used initially. If the Observed Defect Rate (ODR) is less than the AQL, the Minimum Surveillance Level may be used. If, at the Minimum Surveillance Level, the ODR exceeds the AQL, inspections should then return to the Normal Surveillance Level. If, at the Normal Surveillance Level, the ODR exceeds the AQL for two consecutive months, the taking of additional samples should be considered.

#### 5. Sample Size:

Minimum Surveillance: 10% of the Exit Signs and Emergency Lights

Normal Surveillance: 20% of the Exit Signs and Emergency Lights

The percentage of samples and the number of inspections that arise from them may be adjusted based upon changing conditions and local requirements.

- 6. <u>Sampling Procedures</u>: On a scheduled basis, the COTR will randomly select approximately 20% of the exit signs and emergency lights to sample under Normal Surveillance. If Minimum Surveillance is being applied, the COTR will randomly select approximately 10% of the exit signs and emergency lights for surveillance.
- 7. <u>Evaluation Procedures</u>: The COTR will verify that the work is performed in accordance with the specifications and specified time frames. A timeliness defect is the percentage of time that work is

completed or responded to, as appropriate, past the KO approved or PRS-specified timeliness requirement. Each output that does not meet the specified requirements will constitute a defect.

- a. Planned Inspections. For each exit sign or emergency light selected, the COTR will travel to the location to determine whether the SP performed the work and completed the work within the specified time frames. A preprinted Evaluation Worksheet will be completed at the time of the evaluation of the service.
- b. Incidental Inspection Performance. If defective conditions are discovered which are not part of the planned inspections, a separate Evaluation Worksheet will be annotated with the same information as a regular worksheet, noting that this is an incidental inspection. When a trend in defects is noted during the course of regular scheduled inspections, incidental inspections may also be used to determine the magnitude of the defects for this specific work item.
- 8. <u>Analysis of Results</u>: At the end of the month, the COTR will use the Evaluation Summary sheet to summarize all the information on the Evaluation Worksheets and compute the ODR for each performance indicator. The ODR is calculated by dividing the total number of observed by the total population of services so that:

- 9. <u>Suggested Action</u>: The SP should be notified monthly as to whether work performance has been satisfactory or not. If the SP's performance was unsatisfactory, a Contract Discrepancy Report should be issued and other actions, such as increasing the level of surveillance, may be considered.
- 10. <u>Attachments</u>: Forms to be used in the evaluation process include the evaluation worksheets, evaluation summaries, and Contract Discrepancy Reports. Evaluation worksheets and summaries are included in the Surveillance Plan. The Contract Discrepancy Report is included as Attachment 1.

Contract Title: DPW Operation and Maintenance Activities
Location: Vicksburg, MS
Surveillance Guide Number: 8

1. Contract Requirement: Level II Work Orders

		<u>Performance</u>		
Pe	erformance Indicator	<u>Category</u>	<u>Paragraph</u>	MADR
a.	Perform work in accordance with applicable quality and workmanship standards.	Quality	C.1.6.3.2	4.0%
b.	Perform work in accordance with specified timeframes.	Timeliness	C.1.6.3.2	4.0%
c.	Maintain complete and accurate records of work.	Reporting	C.1.6.3.2	7.0%

- 2. <u>Primary Method of Surveillance</u>: Planned Sampling Supported by Validated Customer Complaints and Incidental Inspections
- 3. Quantity of Work: The quantity of work will vary depending on the requirements performed by the SP in that month.
- 4. <u>Level of Surveillance</u>: The Normal Surveillance Level will be used initially. If the Observed Defect Rate (ODR) is less than the AQL, the Minimum Surveillance Level may be used. If, at the Minimum Surveillance Level, the ODR exceeds the AQL, inspections should then return to the Normal Surveillance Level. If, at the Normal Surveillance Level, the ODR exceeds the AQL for two consecutive months, the taking of additional samples should be considered.

#### 5. Sample Size:

Minimum Surveillance: 10% of the Level II Work Orders

Normal Surveillance: 20% of the Level II Work Orders

The percentage of samples and the number of inspections that arise from them may be adjusted based upon changing conditions and local requirements.

- 6. <u>Sampling Procedures</u>: On a scheduled basis, the COTR will select approximately 20% of the Level II work orders to sample under Normal Surveillance. If Minimum Surveillance is being applied, the COTR will select approximately 10% of the Level II work orders for surveillance. The sample will contain all Emergency, Urgent, and High Priority work orders, with the balance of the sample consisting of Routine priority work orders.
- 7. Evaluation Procedures: The COTR will verify that the work is performed in accordance with the

specifications and specified time frames. A timeliness defect is the percentage of time that work is completed or responded to, as appropriate, past the KO approved or PRS-specified timeliness requirement. Each output that does not meet the specified requirements will constitute a defect.

- a. Planned Inspections. For each Level II work order selected, the COTR will determine whether the SP completed the work within the required time frame and performed work in accordance with applicable professional and quality standards. A preprinted Evaluation Worksheet will be completed at the time of the evaluation of the service.
- b. Incidental Inspection Performance. If defective conditions are discovered which are not part of the planned inspections, a separate Evaluation Worksheet will be annotated with the same information as a regular worksheet, noting that this is an incidental inspection. When a trend in defects is noted during the course of regular scheduled inspections, incidental inspections may also be used to determine the magnitude of the defects for this specific work item.
- c. Customer Complaints. Upon receipt of the customer complaint, the COTR will: evaluate the complaint, document legitimate complaints, notify the SP of the complaint, request input from the SP regarding any required corrective action, and inform the SP of any further corrective action necessary.
- 8. <u>Analysis of Results:</u> At the end of the month, the COTR will use the Evaluation Summary sheet to summarize all the information on the Evaluation Worksheets and compute the ODR for each performance indicator. The ODR is calculated by dividing the total number of observed by the total population of services so that:

- 9. <u>Suggested Action</u>: The SP should be notified monthly as to whether work performance has been satisfactory or not. If the SP's performance was unsatisfactory, a Contract Discrepancy Report should be issued and other actions, such as increasing the level of surveillance, may be considered.
- 10. <u>Attachments</u>: Forms to be used in the evaluation process include the evaluation worksheets, evaluation summaries, Customer Complaint Records, and Contract Discrepancy Reports. Evaluation worksheets and summaries are included in the Surveillance Plan. The Customer Complaint Record is included as Attachment 1. The Contract Discrepancy Report is included as Attachment 2.

Contract Title: DPW Operation and Maintenance Activities
Location: Vicksburg, MS
Surveillance Guide Number: 9

Contract Requirement: Level III Work Orders

		<u>Performance</u>		
Pε	erformance Indicator	<u>Category</u>	<u>Paragraph</u>	MADR
a.	Perform work in accordance with applicable quality and workmanship standards.	Quality	C.1.6.3.3	4.0%
b.	Perform work in accordance with specified timeframes.	Timeliness	C.1.6.3.3	4.0%
C.	Maintain complete and accurate records of work.	Reporting	C.1.6.3.3	7.0%

- 2. <u>Primary Method of Surveillance</u>: Planned Sampling Supported by Validated Customer Complaints and Incidental Inspections
- 3. Quantity of Work: The quantity of work will vary depending on the requirements performed by the SP in that month.
- 4. <u>Level of Surveillance</u>: The Normal Surveillance Level will be used initially. If the Observed Defect Rate (ODR) is less than the AQL, the Minimum Surveillance Level may be used. If, at the Minimum Surveillance Level, the ODR exceeds the AQL, inspections should then return to the Normal Surveillance Level. If, at the Normal Surveillance Level, the ODR exceeds the AQL for two consecutive months, the taking of additional samples should be considered.

#### 5. Sample Size:

Minimum Surveillance: 10% of the Level III Work Orders

Normal Surveillance: 20% of the Level III Work Orders

The percentage of samples and the number of inspections that arise from them may be adjusted based upon changing conditions and local requirements.

- 6. <u>Sampling Procedures</u>: On a scheduled basis, the COTR will select approximately 20% of the Level III work orders to sample under Normal Surveillance. If Minimum Surveillance is being applied, the COTR will select approximately 10% of the Level III work orders for surveillance. The smple will contain all Emergency, Urgent, and High Priority work orders, with the balance of the sample consisting of Routine priority work orders.
- 7. Evaluation Procedures: The COTR will verify that the work is performed in accordance with the

specifications and specified time frames. A timeliness defect is the percentage of time that work is completed or responded to, as appropriate, past the KO approved or PRS-specified timeliness requirement. Each output that does not meet the specified requirements will constitute a defect.

- a. Planned Inspections. For each Level III work order selected, the COTR will determine whether the SP completed the work within the required time frame and performed work in accordance with applicable professional and quality standards. A preprinted Evaluation Worksheet will be completed at the time of the evaluation of the service.
- b. Incidental Inspection Performance. If defective conditions are discovered which are not part of the planned inspections, a separate Evaluation Worksheet will be annotated with the same information as a regular worksheet, noting that this is an incidental inspection. When a trend in defects is noted during the course of regular scheduled inspections, incidental inspections may also be used to determine the magnitude of the defects for this specific work item.
- c. Customer Complaints. Upon receipt of the customer complaint, the COTR will: evaluate the complaint, document legitimate complaints, notify the SP of the complaint, request input from the SP regarding any required corrective action, and inform the SP of any further corrective action necessary.
- 8. <u>Analysis of Results</u>: At the end of the month, the COTR will use the Evaluation Summary sheet to summarize all the information on the Evaluation Worksheets and compute the ODR for each performance indicator. The ODR is calculated by dividing the total number of observed by the total population of services so that:

- 9. <u>Suggested Action</u>: The SP should be notified monthly as to whether work performance has been satisfactory or not. If the SP's performance was unsatisfactory, a Contract Discrepancy Report should be issued and other actions, such as increasing the level of surveillance, may be considered.
- 10. <u>Attachments</u>: Forms to be used in the evaluation process include the evaluation worksheets, evaluation summaries, Customer Complaint Records, and Contract Discrepancy Reports. Evaluation worksheets and summaries are included in the Surveillance Plan. The Customer Complaint Record is included as Attachment 1. The Contract Discrepancy Report is included as Attachment 2.

## SURVEILLANCE GUIDE # 1 EVALUATION WORKSHEET

Contract Requirement: (	0001A - Pre	epare and	Provide Si	ubmittals (Phase-In Period)	
Type of Inspection:	100%	Planned	dIr	ncidental	Month
Quality Indicator:			Timeliness Ind		Reporting Indicator:
Prepare submittals in accordance	with the PWS.		Prepare al frame.	Il records and reports within the specified time	
PWS Paragraph: C.1.5.2.2, C.1.5.3, C.1.7.2, C.1.7.5, C C.1.8.7	C.1.5.4, C.1.6.4.6, C C.1.7.6, C.1.7.3, C.1.8	C.1.6.6, 3.1, C.1.8.5,	PWS Paragra	ph:C.1.5.2.2, C.1.5.3, C.1.5.4, C.1.6.4.6, C.1.6.6, C.1.7.2, C.1.7.5, C.1.7.6, C.1.7.3, C.1.8.1, C.1.8.5, C.1.8.7	PWS Paragraph:
		tisfactory; U=U	nsatisfactory		
Date	Quality	Timeliness	Reporting	Comments:	
	·				
Total Inspections for the P	eriod:	Total Uns	atisfactory:	COTR:	Date:
				(Signature)	

## SURVEILLANCE GUIDE # 2 EVALUATION WORKSHEET

Contract Requirement.	0002AA - PI	ераге, імаі	ntain, and	Provide Records, Reports, and	Submittals
Type of Inspection:	100%	Planned	dIr	ncidental	Month
Quality Indicator:  Prepare, submit, and maintain complete and accurate records and reports.		Timeliness Ind Prepare al frame.	icator: I records and reports within the specified time	Reporting Indicator:	
	, C.1.6.12, C.1.7.2, C. 5, C.1.7.6, C.1.8.1, C. C.1.9, C.1.10	1.7.3, 1.8.3,	-	ph:C.1.5.2.2, C.1.5.3, C.1.5.4, C.1.6.4.6, C.1.6.7, C.1.6.8, C.1.6.10, C.1.6.12, C.1.7.2, C.1.7.3, C.1.7.4.1, C.1.7.5, C.1.7.6, C.1.8.1, C.1.8.3, C.1.8.5, C.1.8.7, C.1.9, C.1.10	PWS Paragraph:
		tisfactory; U=U	1		
Date	Quality	Timeliness	Reporting	Comments:	
Total Inspections for the I	Period:	Total Uns	atisfactory:	COTR:(Signature)	Date:

## SURVEILLANCE GUIDE # 3 EVALUATION WORKSHEET

Contract Requirement: 0002AB - Clean Debris From Around Gates and Hydraulic Barriers								
Type of Inspection:	100%	Planned	dIr	ncidental	Month			
Quality Indicator:  Perform work in accordance with all applicable professional and quality standards.			Timeliness Indicator:  Perform work in accordance with required time frames.		Reporting Indicator:			
PWS Paragraph: C.5.1.2.1			PWS Paragra	ph:C.5.1.2.1	PWS Paragraph:			
		tisfactory; U=U						
Date	Quality	Timeliness	Reporting	Comments:				
Total Inspections for the Pe	eriod:	Total Uns	atisfactory:	COTR:(Signature)	Date:			

## SURVEILLANCE GUIDE # 4 EVALUATION WORKSHEET

Contract Requirement: 000	D2AC - Tre	eat Sanitar	y Sewer M	lanholes and Lift Stations		
Type of Inspection:	100%	Planned	dIr	ncidental	Month	
Quality Indicator:  Perform work in accordance with all a quality standards.	pplicable profess	ional and	Perform m schedule.	licator: naintenance in accordance with specified	Reporting Indicator:	
PWS Paragraph: C.5.2.3.1.1, C.5.2.3.1.2	2		PWS Paragra	ph:C.5.2.3.1.1, C.5.2.3.1.2	PWS Paragraph:	
		tisfactory; U=U				
Date	Quality	Timeliness	Reporting	Comments:		
Total Inspections for the Perio	od:	Total Uns	atisfactory:	COTR:		_ Date:

## SURVEILLANCE GUIDE # 5 EVALUATION WORKSHEET

Type of Inspection:	_100%	Planned	dIr	ncidental	Month
Quality Indicator:  Perform work in accordance with all a quality standards.	applicable profess	sional and	Perform m schedule.	licator: naintenance in accordance with specified	Reporting Indicator:  Maintain complete and accurate records of work.
PWS Paragraph: C.5.2.3.1.3			PWS Paragra	ph:C.5.2.3.1.3	PWS Paragraph:C.5.2.3.1.3
		tisfactory; U=U			•
Date	Quality	Timeliness	Reporting	Comments:	
	•	<u>.</u>	·		
Total Inspections for the Per	iod:	Total Uns	atisfactory:	COTR:	Date:

## SURVEILLANCE GUIDE # 6 EVALUATION WORKSHEET

Contract Requirement:	0002AE - Ins	pect Aeria	al Distributi	on Lines	
Type of Inspection:	100%	Planned	dIr	ncidental	Month
Quality Indicator:  Perform inspection as specified a deficiencies.	and provide COTR wit	h a list of	Perform in and prepar frame.	icator: spection in accordance with specified schedule re records and reports within the specified time	Reporting Indicator:  Provide complete and accurate records of work.
PWS Paragraph: C.5.2.3.2.2				ph:C.5.2.3.2.2	PWS Paragraph: C.5.2.3.2.2
		tisfactory; U=U			
Date	Quality	Timeliness	Reporting	Comments:	
Total Inspections for the F	Period:	Total Uns	atisfactory:	COTR: (Signature)	Date:

## SURVEILLANCE GUIDE # 7 EVALUATION WORKSHEET

Type of Inspection:100%		Timeliness India  Perform ins and prepare frame.  PWS Paragrap	cator: spection in accordance with specified schedule e records and reports within the specified time	Month  Reporting Indicator:  Provide complete and accurate records of work.  PWS Paragraph: C.5.3.3.2
Perform inspection as specified and provide COTR videficiencies.  PWS Paragraph: C.5.3.3.2  Grades: S=5	Satisfactory; U=U	Perform ins and prepare frame. PWS Paragrap nsatisfactory	spection in accordance with specified schedule e records and reports within the specified time oh:C.5.3.3.2	Provide complete and accurate records of work.
Grades:S=		nsatisfactory		PWS Paragraph:C.5.3.3.2
<u> </u>			Comments:	•
Date Quality	Timeliness	Reporting	Comments:	
	1			
Total Inspections for the Period:	Total Une	atisfactory: _	COTR: (Signature)	Date:

## SURVEILLANCE GUIDE # 8 EVALUATION WORKSHEET

Type of Inspection:	100%	Planned			Month
Quality Indicator:  Perform work in accordance with workmanship standards.	applicable quality an	d	Timeliness Inc Perform w	dicator:  ork in accordance with specified timeframes.	Reporting Indicator:  Maintain complete and accurate records of work.
PWS Paragraph: C.1.6.3.2			PWS Paragra	aph:C.1.6.3.2	PWS Paragraph: C.1.6.3.2
		tisfactory; U=U			
Date	Quality	Timeliness	Reporting	Comments:	
Total Inspections for the F					Date:

## SURVEILLANCE GUIDE # 9 EVALUATION WORKSHEET

Type of Inspection:	100%	Planned			Month
Quality Indicator:  Perform work in accordance with workmanship standards.	applicable quality an	d	Timeliness Inc Perform w	dicator:  ork in accordance with specified timeframes.	Reporting Indicator:  Maintain complete and accurate records of work.
PWS Paragraph: C.1.6.3.3			PWS Paragra	nph:C.1.6.3.3	PWS Paragraph: C.1.6.3.3
		atisfactory; U=U			
Date	Quality	Timeliness	Reporting	Comments:	
Total Inspections for the F					Date:

#### **SURVEILLANCE GUIDE # 1 EVALUATION SUMMARY**

Contract Requirement: 0001A - Prepare and Provide Submittals (Phase-In Period)

PWS Paragraph: C.1.5.2.2 C.1.8.5, (		, C.1.6.4.6,	C.1.6.6, C.1.7	.2, C.1.7.5, C.	1.7.6, C.1.7	7.3, C.1.8.1,
Month						
Method of Inspection						
Surveillance Level This N						
Number of Inspections A	ssigned					
Number of Inspections P	erformed					
Recommended Surveilla						
WORK REQUIREMENTS	POPULATION	SAMPLE	NO. OF DEFECTS	ODR (%)	AQL	QC Rating
Prepare submittals in accordance with the PWS.		100% Inspection			2.5%	
Prepare all records and reports within the specified time frame.		100% Inspection			2.5%	
Overall Evaluation:			_			
Comments						
COTR:			Date			
(Signature)						

#### SURVEILLANCE GUIDE # 2 EVALUATION SUMMARY

Contract Requirement: 0002AA - Prepare, Maintain, and Provide Records, Reports, and Submittals

PWS Paragraph: C.1.5.2.2 C.1.7.4.1	, C.1.5.3, C.1.5.4 , C.1.7.5, C.1.7.6					1.7.2, C.1.7.3,
Month						
Method of Inspection						
Surveillance Level This M	Nonth					
Number of Inspections As	ssigned					
Number of Inspections P	erformed					
Recommended Surveillar	nce Next Month	1	_			
WORK REQUIREMENTS	POPULATION	SAMPLE	NO. OF DEFECTS	ODR (%)	AQL	QC Rating
Prepare, submit, and maintain complete and accurate records and reports.		Planned Sampling			2.5%	
Prepare all records and reports within the specified time frame.		Planned Sampling			2.5%	
Overall Evaluation:			_			
Comments						
COTR:			Date			
(Signature)						

## SURVEILLANCE GUIDE # 3 EVALUATION SUMMARY

Contract Requirement: 0 PWS Paragraph: C.5.1.2.1	002AB - Clean	Debris Fro	om Around Ga	ates and Hyd	raulic Barr	riers
Month						
Method of Inspection			<u> </u>			
Surveillance Level This M	onth		_			
Number of Inspections As	ssigned					
Number of Inspections Pe	erformed		_			
Recommended Surveillar	nce Next Month					
WORK REQUIREMENTS	POPULATION	SAMPLE	NO. OF DEFECTS	ODR (%)	AQL	QC Rating
Perform work in accordance with all applicable professional and quality standards.		100% Inspection			4.0%	
Perform work in accordance with required time frames.		100% Inspection			4.0%	
Overall Evaluation:						
Comments						
COTR:			Date			
(Signature)						

# SURVEILLANCE GUIDE # 4 EVALUATION SUMMARY

Contract Requirement: 0	002AC - Treat	Sanitary So	ewer Manhol	es and Lift St	ations	
PWS Paragraph: C.5.2.3.1.	1, C.5.2.3.1.2					
Month						
Method of Inspection			_			
Surveillance Level This M	onth		_			
Number of Inspections As	ssigned					
Number of Inspections Pe	erformed		<u> </u>			
Recommended Surveillar	nce Next Month	l				
WORK REQUIREMENTS	POPULATION	SAMPLE	NO. OF DEFECTS	ODR (%)	AQL	QC Rating
Perform work in accordance with all applicable professional and quality standards.		Planned Sampling			4.0%	
Perform maintenance in accordance with specified schedule.		Planned Sampling			4.0%	
Overall Evaluation:			<u> </u>			
Comments						
COTR:			Date			
(Signature)						

# SURVEILLANCE GUIDE # 5 EVALUATION SUMMARY Location: Vicksburg, MS

Contract Requirement: 0	002AD - Test F	Fire Hydran	ts			
PWS Paragraph: C.5.2.3.1.	.3					
Month						
Method of Inspection						
Surveillance Level This M						
Number of Inspections As	_					
Number of Inspections Pe			_			
Recommended Surveillar	ice Next Month					
WORK REQUIREMENTS	POPULATION	SAMPLE	NO. OF DEFECTS	ODR (%)	AQL	QC Rating
Perform work in accordance with all applicable professional and quality standards.		Planned Sampling			4.0%	
Perform maintenance in accordance with specified schedule.		Planned Sampling			7.0%	
Maintain complete and accurate records of work.		Planned Sampling			4.0%	
Overall Evaluation:						
Comments						
COTR:			Date			
(Signature)						

# SURVEILLANCE GUIDE # 6 EVALUATION SUMMARY Location: Vicksburg, MS

Contract Requirement: 0	•	ct Aerial Di	stribution Line	es		
PWS Paragraph: C.5.2.3.2	.2					
Month						
Method of Inspection						
Surveillance Level This M	Nonth		<u> </u>			
Number of Inspections As	ssigned					
Number of Inspections Po	erformed					
Recommended Surveillar	nce Next Month	l				
WORK REQUIREMENTS	POPULATION	SAMPLE	NO. OF DEFECTS	ODR (%)	AQL	QC Rating
Perform inspection as specified and provide COTR with a list of deficiencies.		Planned Sampling			4.0%	
Perform inspection in accordance with specified schedule and prepare records and reports within the specified time frame.		Planned Sampling			7.0%	
Provide complete and accurate records of work.		Planned Sampling			4.0%	
Overall Evaluation:			_			
Comments						
COTR:			Date			
(Signature)			·			<del></del>

# SURVEILLANCE GUIDE # 7 EVALUATION SUMMARY

Contract Requirement: 0	002AF - Inspe	ct and Test	Emergency	Lighting Syste	ems and E	Exit Lights
PWS Paragraph: C.5.3.3.2						
Month			<u> </u>			
Method of Inspection			<u> </u>			
Surveillance Level This N	Nonth		<u>—</u>			
Number of Inspections A	ssigned		_			
Number of Inspections P	erformed		<u> </u>			
Recommended Surveilla	nce Next Month	l	_			
WORK REQUIREMENTS	POPULATION	SAMPLE	NO. OF DEFECTS	ODR (%)	AQL	QC Rating
Perform inspection as specified and provide COTR with a list of deficiencies.		Planned Sampling			2.5%	
Perform inspection in accordance with specified schedule and prepare records and reports within the specified time frame.		Planned Sampling			4.0%	
Provide complete and accurate records of work.		100% Inspection			4.0%	
Overall Evaluation:			_			
Comments						
COTR:			Date			
(Signature)						

# SURVEILLANCE GUIDE # 8 EVALUATION SUMMARY Location: Vicksburg, MS

Contract Requirement: 0 PWS Paragraph: C.1.6.3.2	003A - Level	II Work Or	ders			
Month						
Method of Inspection						
Surveillance Level This M						
Number of Inspections As Number of Inspections Pe	_					
Recommended Surveillar						
WORK						
REQUIREMENTS	POPULATION	SAMPLE	NO. OF DEFECTS	ODR (%)	AQL	QC Rating
Perform work in accordance with applicable quality and workmanship standards.		Planned Sampling			4.0%	
Perform work in accordance with specified timeframes.		Planned Sampling			4.0%	
Maintain complete and accurate records of work.		Planned Sampling			7.0%	
Overall Evaluation:						
Comments						
COTR:			Date			
(Signature)			Date			

# SURVEILLANCE GUIDE # 9 EVALUATION SUMMARY

	L	ocation: \	/icksburg, iv	15		
Contract Requirement: 0	003A - Level	III Work O	rders			
PWS Paragraph: C.1.6.3.3						
Month						
Method of Inspection						
Surveillance Level This M						
Number of Inspections As						
Number of Inspections Pe	_					
Recommended Surveillar	nce Next Month		_			
WORK REQUIREMENTS	POPULATION	SAMPLE	NO. OF DEFECTS	ODR (%)	AQL	QC Rating
Perform work in accordance with applicable quality and workmanship standards.		Planned Sampling			4.0%	
Perform work in accordance with specified timeframes.		Planned Sampling			4.0%	
Maintain complete and accurate records of work.		Planned Sampling			7.0%	
Overall Evaluation:						
Comments						
COTR:			Date			

(Signature)